

## FILETTATURA

WHITWORTH BSW (conforme a BS 84-1956 Tolleranza media)

Dimen.	Passo F x 1"	Madrevite		Vite	
		∅ Foratura		∅ Tornitura	
		min.	max.	max	min.
1/4	20	4,744	5,224	6,330	6,000
5/16	18	6,151	6,661	7,918	7,600
3/8	16	7,512	8,052	9,505	9,100
7/16	14	8,809	9,379	11,093	10,700
1/2	12	10,015	10,610	12,675	12,200
5/8	11	12,948	13,598	15,846	15,400
3/4	10	15,831	16,538	19,018	18,500
7/8	9	18,647	19,411	22,190	21,600
1	8	21,375	22,185	25,361	24,800
1 1/8	7	23,976	24,879	28,529	27,900
1 1/4	7	27,151	28,054	31,704	31,000
1 3/8	6	29,558	30,555	34,873	34,100
1 1/2	6	32,733	33,730	38,048	37,300
1 5/8	5	34,834	35,921	41,214	40,300
1 3/4	5	38,009	39,096	44,389	43,500
1 7/8	4 1/2	40,468	41,468	47,557	46,600
2	4 1/2	43,643	44,823	50,732	49,800
2 1/4	4	49,100	50,420	57,072	56,200
2 1/2	4	55,450	56,770	63,422	62,500
2 3/4	3 1/2	60,648	63,108	69,763	68,800
3	3 1/2	66,699	68,459	76,113	75,100